

Ensure the sustainability of your machine

We support you in the modernization of your gravure printing machine



Gravure printing machine Replacement of Simadyn



Problem

In many gravure printing machines, the drive control is still performed by SIMADYN. However, SIMADYN has now been discontinued, the availability of replacement parts is to a certain extent quite critical, and manufacturer support has been withdrawn. Skilled personnel are almost no longer available worldwide.

Solution

Our team of globally experienced engineers and fitters modernizes your plant by replacing the critical SIMADYN components with currently available Siemens state of the art Motion Control components.

Customer benefit

- ✓ State-of-the-art components for drive control
- ✓ Guaranteed spare parts supply
- The first step of an overall retrofit is already completed with this replacement (cost splitting)
- In general, a retrofit means a lower financial and time expenditure in comparison to buy a new machine

*Offer

- 60,000.00 EUR net plus VAT (budget price)
- \cdot EXW plus freight and packaging
- plus installation & commissioning
- Time required: approx. 1 week plus production support of 3 days after conversion

